



Office of Public Housing Real Estate Assessment Center Request for Technical Review (TR) or Database Adjustment (DBA) of a Physical Inspection Score

Inspection Number 44444 **Project ID Number** 8000000
Inspection Date July 15, 2000 **Address of Property** 123 Main Street
Project/Property Name Main Street Apartments **City, State, Zip** Chattanooga, TN
Date of Request July 31, 2000 **Contact Name** Jane Smith
TR or DBA? TR

ISSUE # 1

| Location (Inspectable Area) | Building Number | Unit Number |
|-----------------------------|-----------------|-------------|
| Dwelling Unit | 4 | 48B |

Documentation Type:



Item and Deficiency/Observation

Bathroom Cabinets – Damaged/Missing

Reason for Request

The bathroom cabinets are present and functioning properly. There was no damage at the time of the inspection.

Additional Comments

Picture #2 is date-stamped the day of the inspection, and shows no sign of damage.

ISSUE

| Location (Inspectable Area) | Building Number | Unit Number |
|-----------------------------|-----------------|-------------|
| | | |

Documentation Type:



Item and Deficiency/Observation

Reason for Review

Additional Comments

ISSUE

| Location (Inspectable Area) | Building Number | Unit Number |
|-----------------------------|-----------------|-------------|
| | | |

Documentation Type:



Item and Deficiency/Observation

Reason for Review

Additional Comments